Ref. No: Date: Subject: 0255 12/09/23 RAAC

## **REQUEST**

- 1. Has reinforced autoclaved aerated concrete (RAAC) been identified in the Trust?
- 2. Has any assessment been made of RAAC structural strength? Please share these with us.
- 3. Have any risks assessments been completed in line with Regulation 3 of The Management of Health and Safety at Work Regulations 1999? Please share these with us.
- 4. Who is the key officer or expert in the Trust with whom we can further liaise directly about safety of the estate?
- 5. What mitigations have been made and proposed? Please share with us a timescale of completed and planned works.
- 6. What are the plans for evacuation? What would the trigger point for evacuation be? How would doctors will be affected under these plans?
- 7. Are there, or may there be, circumstances of danger which may be reasonably believed to be serious and imminent?

## RESPONSE

- Has RAAC been identified in the trust? no
- Has any assessment been made of RAAC structural strength? Please share these with us. Not applicable
- Have any risks assessments been completed in line with <u>Regulation 3</u> of <u>The Management of Health and Safety at Work Regulations 1999?</u>
  Please share these with us. <u>Not applicable</u>

- Who is the key officer or expert in the trust with whom we can further liaise directly about safety of the estate? No RAAC issues exist. The Director responsible for estates is Nicola Bunce Director of Corporate services.
- What mitigations have been made and proposed? Please share with us a timescale of completed and planned works. Not applicable
- What are the plans for evacuation? What would the trigger point for evacuation be? How would doctors will be affected under these plans? Not applicable
- Are there, or may there be, circumstances of danger which may be reasonably believed to be serious and imminent? Not applicable